

STATE OF UTAH
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING
1594 West North Temple - Suite 1210
Box 145801
Salt Lake City, Utah 84114-5801
Telephone: (801) 538-5291
Fax: (801) 359-3940

ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

I. General Information

1. Report Time Period: From (mo./yr.) January 1 2005 To (mo./yr.) December 31 2005
 2. DOGM File Number (Mine No): M /450 /006
 3. Mine Name: FiveMile Pass
 4. Mineral(s) Mined (or permitted to mine): Clay
 5. Type of mine: ☒ Surface Mine or ☐ Underground Mine
 6. Legal Description (Location of Lands Affected):
1/4, 1/4, 1/4, Section 6, Township 7S, Range 3W
1/4, 1/4, 1/4, Section 4, Township 7S, Range 3W
1/4, 1/4, 1/4, Section 32, Township 6S, Range 3W
 7. Name of Operator or Company: Pabco Building Products LLC dba Interstate Brick
 8. Permanent Street Address: 9780 South, 5200 West
City, State, Zip: West Jordan, Utah 84088
Phone: 801-280-5200 Fax: 801-280-5225
 9. Company Representative (or designated operator):
Name: John Hewitt
Title: Assistant Plant Mgr.
Business Address: 9780 South 5200 West
City, State, Zip: West Jordan, UT 84088
Phone: 801-280-5230 Fax: 801-280-5245
- ☒ Please check if any of the above information has changed since previous year.

II. Mining and Reclamation

1. Was there any mine related activity during the past year? ☒ Yes ☐ No
2. If no - what was the last year of activity? _____
3. If yes - how much ore or mineral was mined? Approx. 15,000 tons

Reviewed
12/10/06
PBB

RECEIVED

JAN 31 2006

DIV. OF OIL, GAS & MINING

4. Briefly describe the type of work performed, volume of material moved, and any new or additional surface disturbances that occurred during the past year.
Approximately 2 acres of overburden was removed in the eastern portion of the pit. The overburden was staged on the north wall for later grading and seeding. Approximately 15,000 tons of clay was mined
5. How much **additional acreage** was disturbed during the past year? Approximately 1 acre.
6. How much acreage was **reclaimed** during the past year? none
7. Briefly describe the reclamation work performed during the past year. This description should include methods employed, and an evaluation of the results.
All overburden removed was staged on the north wall of the pit and is ready to be pushed in and regraded per the mine plan.
8. What is the **total** disturbed acreage of entire project at years end? Approx 17 acres. 10.6 acres in the pit & 6.4 acres in piles
9. Briefly summarize any mining and/or reclamation plans for the upcoming year.
Mining will take place winter and fall of 2006. Mining will continue to take place in the eastern end of the pit.


NOTE: Section III., "Additional Information" applies only to **large mining operations.**

III. Additional Information - R647-4-121.2 and .3

1. **The operator shall include an updated map depicting surface disturbance and reclamation performed during the year**, prepared in accordance with Rule R647-4-105.
2. The operator shall keep and maintain timely records relating to his performance under the Act, and shall make these records available to the Division upon request.

IV. Signature Requirement

I hereby certify that the foregoing is true and correct.

Name (Typed or Print): John Hewitt
 Title of Operator: Assistant Plant Mgr.
 Signature of Operator: 
 Date: 1-31-06

